

**TECHNICAL INFORMATION**

SEIKO EPSON CORP, Printer Technical Support Group

☐ H/W SUPPORT

☐ S/W,F/W SUPPORT

Authorized by / T.Nakai,Mgr

☒ MANUAL/STK

☐ AS-TOOL

Approved by / R.Kondo,Amgr

☐ GENERAL

Issued by / T.Minamoto

☐ <<URGENT>>

Please take immediate action with highest priority

☐ <<IMPORTANT>>

Please make sure all necessary actions are taken care of

<<CONFIDENTIALITY RANK>>

☐ Rank S  
(ESC/Internal only)

☒ Rank D  
(open to dealers)

☐ Rank U  
(Public)

---

Model: Stylus CX3500 / CX3600 / CX3650 / CX4500 / CX4600

SUBJECT: Revision of the adjustment program (Ver.1.6)

---

Description

**1. Applicable program**

Stylus CX3500 / CX3600 / CX3650 / CX4500 / CX4600 adjustment program (Ver.1.6)

**2. Operating Environment**

[OS]

Windows 98 / Me / 2000 / XP

[I/F]

USB

**3. Revised contents**

- Revision of the problem that the ink out error occurs when the destination setting for EAI Latin is input.

**4. Other**

As for the adjustment program, please download from the EPSON TechExchange system.

---

Service Report No. SR00894

S/B Issue: ☒ No ☐ Yes (S/B No. P-)

---